

Report No. 14 CIA/PIR 75054

DATE OCTOBER 1966

GROUP 1
Excluded from automatic
downgrading and declassification

SECRET

Approved For Release 2003/03/04 : CIA-RDP78T0516 A001200010036-7

25X1

Approved For Release 2003/03/04: CIA-RDP78T05161A001200010036-7

WARNING

This document commins information effecting the national difference of the United States, within the meaning of Title 18, sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law.

RECORD COPY			COPY NO.	PUB. DATE		LOCATION	i .		MAST	ER	DATE RECEIVED .						
			DISPOSITI	on DATE (S)	ase	2003/0	3/04 :	STOC	K RDP	78T0	MINIMUM 5161A001200010036-7	MAXIM	IUM	10			
CUT TO COPIES O DATE 1-73 CUT TO COPIES			COPIES		DATE		COPIES DESTROYED										
CUT COP I			DATE	CUT TO COPIES		DATE											
CUT COP I			DATE	MASTER		DATE											
0	ATE				NUM	BER OF C	OPIES		DATE		DECELVED OF LOCUED		NUMBE	R OF C	OPIES		
мо.	DAY	YR.	RECEIVED OR	ISSUED	REC'	D ISS'D	BAL	MO.	DAY	YR.	RECEIVED OR ISSUED		REC D	ISS'D BAL			
11	16	66	Dist. Unit	#39-48	10		10										
8	12	68	RPIC #4.4	9 103-105	5	1	15				184910						
8	9	72	Lest # 39	-49, 4,							24942						
			103-105				0	W	K	6	209852						
											170 (500)						
												<u></u>		-			
			7505.5	ed For Pol		2003/0	2/04 -	CIA		70.	5161A001200010036-7	,					
TITL	ε N.	PIC	· · · · · · · · · · · · · · · · · · ·	YOU FOI ROM	<i>1450</i>	-2003/ 0	13/U4 		CLAS		LOCATION			<u> </u>	L		
X1.			1.		Nov	. 196	6	Ţ	s/		l	24	74.	ر ر <u>2</u>	25X1		

DATE		1	RECEIVED OR ISSUED	NUMB	ER OF C	R OF COPIES		DATE			NUME	NUMBER OF COPIES REC'D ISS'D BAL	
MO.	DAY	YR.			ISS'D	1	MO. DAY YR.				REC'D	Iss'D	BAL
			Approved For Re	lease	2003/0	3/04 :	CIA	RDF	78T	05161A001200010036-7			
	[
			Approved For Re	ease	2003/0	3/04 :	CIA	-RD	781	05161A001200010036-7			
717L	: <u>N</u>	PIC			1966				ss.	LOCATION			25X ⁻

	RECORD COPY		COPY NO.	PUB. DATE		LOCATION	٧		MASTER DATE RECEIVED LOCATION								
DISPOSITION DATE (S)						2003/	13/0 <i>4</i> ·	STOCK CIA-RDP78T05161A001200				n1200D1	0036-7	MAXIMUM	9		
CUT COP		0	Jan, 1973	CUT TO COPIES		DATE COPIES DESTROYED						.0000	J-1 /				
CUT COP			DATE	CUT TO COPIES		DATE						,					
	CUT TO COPIES		DATE	MASTER		DATE											
	DATE		RECEIVED OR	ISSUED		BER OF C	OPIES	DATE			BECI	FIVED OR	recuen	NUMBER OF COPIES			
мо.	DAY	YR.	MEGETTED ON	133020	REC	'D ISS'D	BAL	MO.	DAY	YR.	n.c.	RECEIVED OR ISSUED		REC'D	135'D	BAL	
5	22	68	Dist. Unit		9		9										
10	20	12	Dest 9	Opies			0	W	X	6							
			· ·				-										
																-	
	-																
			·														
												-					
							_										
						2000/	20/04	214	200	707	2540480	2400004	2000 7	,			
TITL	E N			ved For Rel		s 2003/ S/	93/04 :	GIA	HDF	7811	<u>)5161∆u</u>				اـــــا	25X1	
	P.	IR-7	5054 RPT.#14	OCT. 196	6	1						5	05	475		\searrow	

DATE			RECEIVED OR ISSUED	NUMB	MBER OF COPIES		}	MO. DAY YR. RECEIVED OR ISSUED	DATE		E PECELVED OF ACCUED		NUMBER OF COP		
10.	DAY	YR.	RECEIVED ON 1330ED	REC'D	ISS'D	BAL	мо.	DAY	YR.	RECEIVED OR ISSUED	REC'D	ISS'D	BAL		
			Approved For Re	lease	2003/0	3/04 :	CIA	-RDF	787	05161A001200010036-7					
				1							_				
				+							+ -				
	_				-	-	-	<u> </u>			+				
				-		<u> </u>		<u> </u>							
		<u> </u>													
		-1													
										,					
\exists				 							- 				
\dashv				 						_					
-				 		·					4				
		-		ļ	ļ										
_				1					_						
			Approved For Pe	0250	200310	2/04 -	CIA	PD!	797	05464004200040036-7					
ITL	E	NPIC	Approved For Re	 C43 	S	, , , , , , , , , , , , , 	OIA	יושר	70	105161A0012 00010036-7		L	257		


CIA IMAGERY ANALYSIS DIVISION

PIR - 75054


PREFACE

This report summarizes significant items of photo intelligence relating to the North Vietnamese railroad system which has been developed from available photography (received by the CIA Imagery Analysis Division) during the period indicated on the cover. This report is intended to provide a comprehensive view of the railroad system and does not necessarily reflect the most recent status changes as reported by pilots' reports or field photo intelligence cables.

The railroad system has been broken down into 5 major lines: the Hanoi/Lao Cai Line, the Hanoi/Dong Dang Line, the Hanoi/Haiphong Line, the Hanoi/Dong Hoi Line and the Thai Nguyen Line (Figure I). Annotated maps and photos are used to show the status of each line...



PIR 750**25X1** FIGURE 1



SECRET
Approved For Release 2003/\(\phi\)3/04 : CIA-RDP7\(\text{8T05161A001200010036-7}\)

CIA IMAGERY ANALYSIS DIVISION


PIR 75054

SUMMARY

Those portions of the Hanoi/Dong Dang, Hanoi/Haiphong and Thai Nguyen Rail Lines covered by interpretable photography are open to through traffic. The Hanoi/Lao Cai Rail Line is interdicted in 4 places, and the Hanoi/Dong Hoi Rail Line is interdicted in 18 places.

CONTENTS

Hanoi/Lao Cai Rail Line	Page	4
Hanoi/Dong Dang Rail Line	3	П
Hanoi/Dong Hoi Rail Line		12
Hanoi/Haiphong Rail Line		17
Thai Nguyen Rail Line		19



25X1

SECRET

CIA IMAGERY ANALYSIS DIVISION

PIR 75054

25X1

ITEM OF INTEREST NO. 1: Hanoi/Lao Cai Rail Line

NAME

: Viet Tri Railroad Ferry

BE

: NA

COORDINATES

: 21 17N - 105 26E, WJ 462550

PHOTO REFERENCE

()

MAP REFERENCE


: JOG (A) 1501, NF 48-10

25X1

25X1

Photography reveals a serviceable rail ferry approximately 0.2 nm W of the destroyed Viet Tri Railroad and Highway Bridge at UTM WJ 465551 (Figure 4). A possible rail ferry-boat is located 0.1 nm E of the bridge at UTM WJ 468550 under some over-hanging trees. A confirmed rail ferryboat measuring approximately 110' x 20' is located about 0.8 nm E of the bridge at UTM WJ 475560, (Figure 3).

Construction has been undertaken on 4 new ferry approaches (i.e., 2 on either side of the river) approximately 0.2 nm W of the serviceable ferry (Figure 4). Ties have been laid on parts of the two southern approaches, but work has been hampered by high water on the northern approaches. Construction has not commenced on the ferry slips.




-5-

SECRET

Approved For Release 2003/03/04 SECRET RDP78T05161A001200010036-7

25X1

PIR 75054 F**IGU**RE 4



-6-

Approved For Release 2003/03/8FCBFTRDP78T05161A001200010036-7

CIA IMAGERY ANALYSIS DIVISION

PIR 75054

25X1

ITEM OF INTEREST NO. 2: Hanoi/Lao Cai Rail Line

NAME

: Pho Hop RR. Bridge

BE

:

25X1

25X1

COORDINATES

: 21 49N - 104 45E, VK 752127


PHOTO REFERENCE

: |

MAP REFERENCE

: JOG (A) 1501, NF 48-10

Photography reveals that 1 span of the 3-span deck-beam Pho Hop Railroad Bridge has been heavily damaged and is undergoing repair. The bridge is currently unserviceable.



25X

Approved For Release 2003/03/8FCRETRDP78T05161Ap01200010036-7

CIA IMAGERY ANALYSIS DIVISION

PIR 75054

25X1

25X1

ITEM OF INTEREST NO. 3: Hanoi/Lao Cai Rail Line

NAME

: Khe Se RR. Bridge

BE

:

25X1

COORDINATES

: 22 00N - 104 33E, VK 538330


PHOTO REFERENCE

MAP REFERENCE

: JOG (A) 1501, NF 48-6

Photography reveals that the single-span half-through truss Khe Se Railroad Bridge is unserviceable. One abutment has been destroyed and the span has been dropped.

25X1



Approved For Release 2003/0**\$66RET**A-RDP78T05161A001200010036-7

CIA IMAGERY ANALYSIS DIVISION

PIR 75054

ITEM OF INTEREST NO. 4: Hanoi/Lao Cai Rail Line

25X1

25X1

NAME : Lang Khay RR. Bridge

BE

.

COORDINATES


: 22 OlN - 104 31E, VK 509359

PHOTO REFERENCE

MAP REFERENCE

: JOG (A) 1501, NF 48-6

Photography reveals that the 3-span, deck-type Lang Khay Railroad Bridge has been repaired and is now serviceable.



Approved For Release 2003/03 AFC RDP78T05161A001200010036-7

PIR 75054

25X1

25X1

CIA IMAGERY ANALYSIS DIVISION

25X1

ITEM OF INTEREST NO. 5: Hanoi/Lao Cai Rail Line

NAME

: Lang Bun RR. Bridge

BE

:

COORDINATES

: 22 09N - 104 23E, VK 368493

PHOTO REFERENCE


•

MAP REFERENCE


: JOG (A) 1501, NF 48-6

Photography reveals that the 8-span, deck-beam Lang Bun Railroad Bridge is undergoing repairs and is unserviceable.

25X1



-10-



Approved For Release 2003/03/42-RDP78T05161A001200010036-7

PIR 75054

25X1

25X1

25X1

CIA IMAGERY ANALYSIS DIVISION

ITEM OF INTEREST NO. 1: Hanoi/Dong Hoi Rail Line

NAME

: Dien Chau RR. Bridge

BE

:

COORDINATES


: 18 58N - 105 35E, WF 613978

PHOTO REFERENCE

: JOG (A) 1501, NE 48-7

MAP REFERENCE

Additional bomb damage is noted on Dien Chau Railroad Bridge. All 8 spans of the bridge are now damaged or destroyed. Three deck-beam spans had been destroyed previously. The remaining original half-through truss span has now been partially dropped. In addition, four deck-beam spans and 4 temporary piers have been destroyed.



25X1

-13-

Approved For Release 2003/03 PACREA-RDP78T05161A001200010036-7

CIA IMAGERY ANALYSIS DIVISION

PIR 75054

25X

25X1

ITEM OF INTEREST NO. 2: Hanoi/Dong Hoi Rail Line

NAME

: Long Ngoc RR. Bridge

BE

:

COORDINATES

: 19 05N - 105 35E, WG 628112

PHOTO REFERENCE

:

MAP REFERENCE

: JOG (A) 1501, NE 48-3

25X1

Photography reveals the center span of the 3-span, deck-type Long Ngoc Railroad Bridge has been destroyed.



Approved For Release 2003/03 SECRET_RDP78T05161A001200010036-7

25X1

CIA IMAGERY ANALYSIS DIVISION

PIR 75054

25X1

25X1

ITEM OF INTEREST NO. 3: Hanoi/Dong Hoi Rail Line

NAME

: Qui Vinh By-Pass No. 2 RR. Bridge

ΒE

:

COORDINATES


: 19 15N - 105 41E, WG 720302

PHOTO REFERENCE

MAP REFERENCE

: JOG (A) 1501, NE 48-3

Photography reveals that the 16-span, trestle-type Qui Vinh By-Pass No. 2 Railroad Bridge has been heavily damaged and is unserviceable. Five spans appear to have been destroyed and 3 spans have been dropped. The bridge is currently undergoing repair. The two alternate railroad bridges at this river crossing are also unserviceable.



-15-

Approved For Release 2003/0364 RETA-RDP78T05161A001200010036-7

CIA IMAGERY ANALYSIS DIVISION

PIR 75054

25X1 ITEM OF INTEREST NO. 4: Hanoi/Dong Hoi Rail Line

NAME

: Yen Xa RR. and Hwy. Bridge

BE

:

COORDINATES

: 20 02N - 105 51E, WH 888665

PHOTO REFERENCE

MAP REFERENCE


: JOG (A) 1501, NF 48-15

25X1

Photography reveals that the single-span, half-through truss Yen Xa Railroad Bridge has been damaged and is unserviceable. The decking has been moderately damaged and the bridge is slightly off-center.



PIR 75054 FIGURE 15



Approved For Release 2003/0567ETA-RDP78T05161A001200010036-7

CIA IMAGERY ANALYSIS DIVISION

PIR 75054

25X1

25X1

ITEM OF INTEREST NO. 1: Hanoi/Haiphong Rail Line

: Hai Duong Transshipment Point NAME

NA BE


: 20 57N - 106 17E, XJ 340180 COORDINATES

PHOTO REFERENCE

: JOG (A) 1501, NF 48-15 MAP REFERENCE

It has now been determined that a previously reported rail-to-water transshipment point about 3 nm NW of Hai Duong (Report No. 1) is a coal transloading area. A spur track leads from the main line to a 3-track yard on the west bank of the Song Thai Binh (River). Coal is being transferred between barges and gondola cars, and large quantities of coal are stockpiled in the area.

Coal has also been observed at two other rail-to-water transloading areas. These are at Bac Giang (21 16N - 106 11E, Report No. 8) and Dap Cau (21 12N - 106 06E, Report No. 12).



-18-

KEY

All Maps within this report have been keyed in the following manner:

- ☆ Main bridge bombed now serviceable.
- * By-pass bridge or bridges serviceable.
- ☐ Main bridge unserviceable.
- All bridge crossing facilities unserviceable.
- ▲ By-pass bridge under construction.
- ,__Original bridge has not been damaged or destroyed based on available photography.
- Extent of rail line covered by available, interpretable photography.
- $\ensuremath{\bullet}$ Item of interest. Turn to the item number within the section for further information.

